








Assembling Instruction

(1) bases	(2) Gas Column	(3) Mechanism	A	B
				
(4) Chair-body	(5) Screws			
	<div><div>1.  X4 6X20MM</div><div>2.  X4 6X20MM</div><div>3.  X1 5MM</div></div>			
C 